

3850 HWY 93 S. Kalispell, MT 59901 (o) (406) 755-1915 (f) (406) 755-1913

Estimate: C4681

Customer Name: 6348 - ROBINSON, MERLE L

Address: 2755 US HWY 93 W

WHITEFISH, MT

Phone#(res): (406) 871-1601

Phone#(bus): Cell Phone:

Email: merle@MerleRobinson.com

Date In: 16 JUL 21 **Promised Date:**

Purchased Date: 21 AUG 20 Delivery Date: 21 AUG 20

Author: CRV5 Stock No: 3584 Year: 2017 Manufacturer: LEISURE TRAVEL

Brand: LEISURE TRAVEL

Model: UNITY

Exterior Color: WHITE SUEDE Chassis#: 8BNPF4CC8GE132463

License#: Miles/Hrs: 12288

Job #1 - External

COMPLAINT: CUSTOMER SUSPECTS EITHER A PROPANE LEAK AND/OR CO2/LP DETECTOR IS NOT WORKING AS DESIGNED.

CAUSE: Check system

CORRECTION: Lp detector works as it should. Leak don test found no leaks. Regulator maxed out at 10wc. Changed regulator. Tested for leaks again.

Labor				
Code Z990	Description TROUBLESHOOT PROPANE & DETECTOR	Hours 0.45	Rate 165.00	Total 74.25
Parts —				
Part # 06-0447	Description EXCELA-FLO 2 STAGE REG	Qty 1	Price 24.79	Total 24.79
Other Service	200			
Code SS	Description SHOP SUPPLIES	Qty 1	Price 0.00	Total 0.00
		Subtotal for Joh #1:		99 04

Job #2 - External

CUSTOMER HAS EXTENDED WARRANTY:

RV ELITE

CONTRACT# 6462132463 DEDUCT: 100.00

1-800-297-0256

Subtotal for Job #2:	0.00
Parts Total:	24.79
Labour Total:	74.25
Sublet Total:	0.00
Extras Total:	0.00
MONTANA SALES TAX:	0.00
Estimate Total:	99.04

