



3850 HWY 93 S.
Kalispell, MT 59901

(o) (406) 755-1915
(f) (406) 755-1913

Estimate: C4681

Customer Name: 6348 - ROBINSON, MERLE L
Address: 2755 US HWY 93 W
WHITEFISH, MT
Phone#(res): (406) 871-1601
Phone#(bus):
Cell Phone:
Email: merle@MerleRobinson.com

Date In: 16 JUL 21
Promised Date:
Purchased Date: 21 AUG 20
Delivery Date: 21 AUG 20

Author: CRV5
Stock No: 3584
Year: 2017
Manufacturer: LEISURE TRAVEL
Brand: LEISURE TRAVEL
Model: UNITY

Exterior Color: WHITE SUEDE
Chassis#: 8BNPF4CC8GE132463
Serial#:
License#:
Miles/Hrs: 12288

Job #1 - External

COMPLAINT: CUSTOMER SUSPECTS EITHER A PROPANE LEAK AND/OR CO2/LP DETECTOR IS NOT WORKING AS DESIGNED.

CAUSE: Check system

CORRECTION: Lp detector works as it should. Leak don test found no leaks. Regulator maxed out at 10wc. Changed regulator. Tested for leaks again.

Labor

Code	Description	Hours	Rate	Total
Z990	TROUBLESHOOT PROPANE & DETECTOR	0.45	165.00	74.25

Parts

Part #	Description	Qty	Price	Total
06-0447	EXCELA-FLO 2 STAGE REG	1	24.79	24.79

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1	0.00	0.00

Subtotal for Job #1: 99.04

Job #2 - External

CUSTOMER HAS EXTENDED WARRANTY:
RV ELITE
CONTRACT# 6462132463 DEDUCT: 100.00
1-800-297-0256

Subtotal for Job #2: 0.00

Parts Total:	24.79
Labour Total:	74.25
Sublet Total:	0.00
Extras Total:	0.00
MONTANA SALES TAX:	0.00
Estimate Total:	99.04



Estimate: C4681 ROBINSON, MERLE L