

Your Authorized Mercedes Benz Bealer (406) 721-4000 Po Box 8939 Missoula Mt 50808



DAN MARCU	S		VEHICLE ID					TE/TIME IN	DATE OUT	INVOICE NO
101 CANNAL STREE!			8BNPF4CC8	9912	9912	05/0		3 05/06/19	29662	
BIGFORK, M	IGFORK, MT 5991			VEHICLE DES	CRIPTION			TAG NO.	STATUS	
ANMARC@CHARTER.NET			2016 MERCEDES-B SPRINTER 3				00457 PARTIAL-COMPI			OMPLETI
CONTROL NO	CONTROL NO. LICENSE PLATE NO.		CUST. LABOR RATE PROD. DATE		IN-SERV DAT	-SERV DATE DELIV. DATE		DELIV. MILE		
037680	037680									Cash
HOME PHONE WORK PHONE		CELL PHONE STOCK NO						RO COMMENT		
(406) 253-6704		JEFFORY CARRETTA (5						535)		
Line	Line Op-Code Fail		Code Tech Hours Type					Amount		
Cause Correction		WITH U REC/ No.201 r side air	JPDATE OR REC ALL AS RE 7030012				СТИ	RE		
Part N	lumber		Description			Qty				· · · · · ·
M,9068	860150005		DRIVER'S AI	RBA		1				
B *	B * MBSB		А	Custo	mer	\$216.00				
Cause	PRICES VARY PERFORM ME (PLEASE ADV	Y (DIESE RCEDE /ISE CU	EHICLE REQUES EL/SPRINTER/MI S BENZ REQUIF STOMER OF RE nd filter change, fu	LAGE) RED SERVICI COMMENDE	E D SERVIC	ES NEED		e U-	1	
	Performed ins		n, engine oil an xle U-bolts, and		-		acem	ent,		
Part N	lumber		Description			Qty	Un	it Price	Ext. Price	
M,001	M,0019893701USA8		MB GENUIN	E ENGINE O	L 5W-	12		\$13.10	\$157.20	
M,642	M,6421800009		TS FILTER INSERT			1		\$26.40	\$26.40	
,	M,6420906052		FUEL FILTER			1	. :	\$133.00	\$133.00	
,5 12								Total	\$316.60	

				Line Total \$532.60
			Authorized Estimate	9S
Date/Time	Amount	Authorized By	Authorization Method	Phone/Email
05/06/2019 10:13	\$222.48	3	Initial Estimate	

AN MARCUS)		8BNPF4CC8		MILES		9912		FE/TIME IN	DATE OUT	29662
A CANNAL STR		8BNPF4CC8					/19 10:13 05/06/19			
CHORK, MI 599		2016 MERCEDES-B SPRINTE							STATUS	
ANMARC@CHA	LICENSE PLATE NO						00457 PARTIAL-CO		TERMS	
CONTROL NO	LICENSE PLATE NO.	CUST LABOR RATE PROD DATE IN-SER		HA-SERV	UATE	DELIV. DATE D		DELIV. WILES		
037680	MORKBUONE	GELL PHONE	STOCK	<u> </u>		SERV	400		• • • • • • • • • • • • • • • • • • • •	Cash
HOME PHONE	WORK PHONE	GELL PHOINE	5100k				**********	TA (505)	HOC	OMMENT
(406) 253-6704					EFFC	JRY CAR	KKEI	TA (535)	<u> </u>	
14.	#4		1					Totals		
₹	t _a								Amou	
				Labor					\$216	
				Parts Other					\$159	
	Parts-Other Total Amount Due					\$157.20 \$532.60				
					uni Du				————	
				TOTAL AN	MOUNT	T DUE			\$532	2.60
			'							

Thank you for this opportunity to serve you. It is our aim to perform all of the repairs requested on this invoice to you Complete Satisfaction. If our service was satisfactory, tell your friends, if not, please tell us immediatly!

INVOICE

CUSTOMER COPY

Multi Point Inspection Customer: DAN MARCUS VIN: 8 E-mail: DANMARC@CHARTER.NET Plate: VIN: 8BNPF4CC8GE132463 Mileage: 9,912 * Phone: (406) 253-6704* Year/Make/Model: 16 MERCEDE... Checked and OK at this time Requires immediate attention May require future attention MAINTENANCE ITEMS **FLUID LEVELS** DUE DUE OK | FILL OK | FILL Transmission (if Oil & Filter Change Tire Rotation X Engine Oil equipped) Engine/Secondary Power Steering Fuel Filters X Brake Reservoir X Coolant Check Air Filter Minder Transmission Filter X Windshield Washer X Coolant Drain Water Separator Transmission Fluid INTERIOR COMPONENTS Cabin Air Filter **BATTERY CHECK** Dome Light / Amp Light / Dimmer Combination Meter X Cold Cranking Amps Battery Health (good, recharge, bad) (Actual) Parking Brake Operation X Cold Cranking Amps **Battery Condition** (Factory Spec) (clamps, cable. **EXTERIOR COMPONENTS** X Horn Operation **EXTERIOR BODY** Head Lights / Tail Lights / Turn Signals / Brake Lights / Hazards **DRIVER SIDE** / Exterior Lamps **BIRDS-EYE** (3) Windshield Wiper & Washer Operation X PASSENGER SIDE X Windshield Glass (cracks / damage) X Fuel Tank Cap Gasket X Wiper Blades UNDER-VEHICLE COMPONENTS X Engine Air Filter Propeller / Driveshaft (damage/leaks/U-joints) X Drive / CV Shaft (damage/leaks/boots) **TIRES & BRAKES** X Axle Hub & Bearing (damage/leaks/noise) Left Front Right Front X Suspension (damage/leaks/wear) X Tire Wear X Mar Tire Wear X Hoses (cracks/damage/leaks) Pattern/Damage Pattern/Damage Tire Pressure set to Tire Pressure set to Cooling System (leaks) 55 PSI 55 PSI factory-specs factory-specs X Steering Linkage (damage/leaks/wear) X Tread Depth X Tread Depth 9/32" 9/32' X Fluid Leaks (engine/transmission/differential) Brake Lining Brake Lining Exhaust System (damage/leaks/corrosion) X 10mm | DISC 10mm | DĬSC Fuel Lines, Connections, Tank Bands, Vapour Vent System Left Rear Right Rear Hoses (damages/leaks/corrosion) X Tire Wear Tire Wear Drive Belts (cracks/damage/leaks) X Pattern/Damage Pattern/Damage Radiator Core / Air Conditioning Condenser X Tire Pressure set to X Tire Pressure set to factory-specs factory-specs X Tread Depth X Tread Depth **SIGNATURES** 9/32" 9/32" Brake Lining Brake Lining X 10mm | DĬSC 10mm | DISC Wear Indicates **Spare Tire** SERVICE ADVISOR Tire Wear Check Tire Alignment Pattern/Damage Tire Pressure set to **Balance Wheels** factory-specs Tread Depth Tire Repair Needed SERVICE TECHNICIAN

wheels.

COMMENTS

No valve extensions on rear dual wheels, air pressure not checked on rear

Date: 05/06/2019

RO #: 29662

* MULTI-POINT INSPECTION